



FIG. 1


























# F I G. 10

	Fx	Fy	Fz
Rx1	_	0	<u> </u>
Rx2	• +	0	+
Rx3	-	0	+
Rx4	+	0	_
		•	
Ry1	0	. <del>-</del>	_
Ry2	0	+	+
Ry 3.	.0	_	+.
Ry4	0	+	
Rz1	· <u> </u>	0	_
Rz 2	+	0	+
Rz3	_	0	+
Rz4	. +	0	. —






FIG. 12



### FIG. 13







FIG. 15



### F I G. 16




FIG. 17





FIG. 18







FIG. 20






FIG. 23





FIG. 24



F I G. 25




FIG. 26




FIG. 27






FIG. 28



## FIG. 29



## F1G. 30a





FIG. 30b



#### F I G. 31





FIG. 32






FIG. 34




FIG. 35





FIG. 36






FIG. 40





FIG. 41






FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51

<u>300</u>




FIG. 52

